

Clean Project - Delete Unwanted Project Tree Items by selecting Top Level Documents

To run this script

Select **Scripts > Project > Clean_Project_Choose_Top_Level_Docs** from the Menu.

Or, in versions that support the script, you can run the utility directly from this page using this button.

Description

This script cleans up a project by deleting any Graphs, Measurements, Schematics, System Diagrams, Data Files, Netlists, and EM Structures not needed for the current active (not disabled) measurements in the project. This script is commonly used before sending a project to a colleague or to AWR support as an easy way to cut down a complicated project to a much simpler one.

When the script is run, the dialog below will be displayed. Refer to [Clean Project](#) script page and see **Choose Top Level Docs** section for more information

