

Create Sparameter Graphs

To run this script

Select **Scripts > Graphs > Create_Sparameter_Graphs** from the Menus.

Or, in versions that support the script, you can run the utility directly from this page using this button.

Description

This script will create graphs with Sparameter measurements for the existing EM Structures, schematics or data files. The script currently only works for documents with 1 or 2 ports. If the document has more than 2 ports, the script will do nothing.

To use the script, have the document open and the active window and then run the code listed above. Below is a picture of the new graphs added to this project after "Schematic_1" was opened and the active window.

