

# Create Sparameter Graphs

## To run this script

Select **Scripts > Graphs > Create\_Sparameter\_Graphs** from the Menus.

Or, in versions that support the script, you can run the utility directly from this page using this button.

## Description

This script will create graphs with Sparameter measurements for the existing EM Structures, schematics or data files. The script currently only works for documents with 1 or 2 ports. If the document has more than 2 ports, the script will do nothing.

To use the script, have the document open and the active window and then run the code listed above. Below is a picture of the new graphs added to this project after "Schematic\_1" was opened and the active window.

