## **Scripting How-To: Function to get the Active Schematic Window**

```
Function awrGetActiveSchematic As Schematic
 Dim sch As Schematic
 Dim w As Window
 If Not (Project.Schematics Is Nothing) And Not (Project.Schematics.ActiveSchematic Is Nothing) Then
   Set sch = Project.Schematics.ActiveSchematic
   ' unfortunately this does not tell us if the active window is a schematic or a layout. ActiveSchematic will
   ' return the schematic for a layout if a layout window is active so we need to make sure the active window
   ' is actually a schematic
   For Each w In sch.Windows
     If w.Active=True And w.Type<>mwWT_Schematic Then
       'active window is not a schematic
       Set sch=Nothing
    End If
   Next w
   If Not (sch Is Nothing) Then
     Set awrGetActiveSchematic = sch
 End If
End Function
```